

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2483 From entrance to location




Photo # 2484 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2485 Location



Photo # 8486 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2487 Location



Photo # 2488 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2489 Staining in secondary containment



Photo # 2490 Staining in secondary containment



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2491 Tank capacity faded & illegible




Photo # 2492 Tank label contains inaccurate information

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 2493 Open ended load line