

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2024

Submitted Date:

12/04/2024

Document Number:

699506663

**FIELD INSPECTION FORM**

Loc ID 451646 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10694  
Name of Operator: PROVIDENCE OPERATING LLC DBA POCO  
Address: 16400 DALLAS PARKWAY SUITE 400  
City: DALLAS State: TX Zip: 75428

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Grimes, Meghan		mgrimes@providence-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486857	WELL	DG	10/09/2024		001-10579	Barr Lake 21-23-1CDH	DG
486865	WELL	DG	10/10/2024		001-10587	Barr Lake 21-23-2CDH	DG
486866	WELL	DG	10/11/2024		001-10588	Barr Lake 21-23-3CDH	DG
487535	WELL	DG	10/14/2024		001-10604	Buckley 21-16-3CDH	DG
487541	WELL	DG	10/12/2024		001-10609	Buckley 21-16-1CDH	DG
487542	WELL	DG	10/13/2024		001-10610	Buckley 21-16-2CDH	DG

**General Comment:**

Drilling inspection

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 486857 Type: WELL API Number: 001-10579 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 486865 Type: WELL API Number: 001-10587 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 486866 Type: WELL API Number: 001-10588 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487535 Type: WELL API Number: 001-10604 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487541 Type: WELL API Number: 001-10609 Status: DG Insp. Status: DG

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487542 Type: WELL API Number: 001-10610 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: Precision Pusher/Rig Manager: \_\_\_\_\_  
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

**Well Control Equipment:**

Pipe Ram: YES Blind Ram: YES Hydril Type: YES  
 Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/04/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506664	inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815882">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815882</a>