

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/04/2024

Document Number:

699506665**FIELD INSPECTION FORM**Loc ID 485812 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10670

Name of Operator: BISON IV OPERATING LLC

Address: 518 17TH STREET SUITE 1800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ops@bisonog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486047	WELL	WO	08/01/2024		123-52426	Dittmer 01H	WO
486048	WELL	WO	08/01/2024		123-52427	Dittmer 02H	WO
486049	WELL	WO	08/01/2024		123-52428	Dittmer 03H	WO
486050	WELL	WO	08/01/2024		123-52429	Dittmer 04H	WO
486051	WELL	WO	08/01/2024		123-52430	Dittmer 05H	WO
486052	WELL	WO	08/01/2024		123-52431	Dittmer 06H	WO
486053	WELL	WO	08/01/2024		123-52432	Dittmer 07H	WO
486054	WELL	WO	08/01/2024		123-52433	Dittmer 08H	WO
486055	WELL	WO	08/01/2024		123-52434	Dittmer 09H	WO
486056	WELL	WO	08/01/2024		123-52435	Dittmer 10H	WO
486058	WELL	WO	08/01/2024		123-52437	Dittmer 12H	WO
486059	WELL	WO	08/01/2024		123-52438	Dittmer 13H	WO
486060	WELL	WO	08/01/2024		123-52439	Dittmer 14H	WO
486062	WELL	WO	08/01/2024		123-52441	Dittmer 16H	WO

General Comment:

Frac inspection

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID: 486047	Type: WELL	API Number: 123-52426	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486048	Type: WELL	API Number: 123-52427	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486049	Type: WELL	API Number: 123-52428	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486050	Type: WELL	API Number: 123-52429	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486051	Type: WELL	API Number: 123-52430	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486052	Type: WELL	API Number: 123-52431	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486053	Type: WELL	API Number: 123-52432	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486054	Type: WELL	API Number: 123-52433	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486055	Type: WELL	API Number: 123-52434	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486056	Type: WELL	API Number: 123-52435	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486058	Type: WELL	API Number: 123-52437	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486059	Type: WELL	API Number: 123-52438	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486060	Type: WELL	API Number: 123-52439	Status: WO	Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12				
Facility ID: 486062	Type: WELL	API Number: 123-52441	Status: WO	Insp. Status: WO

Well Stimulation

Stimulation Company: Liberty

Stimulation Type: HYDRAULIC FRAC

Observation:

Other:

Maximum Casing Recorded: 10500 PSI

Tubing:

Surface:

Intermediate:

Production: 8900

Instantaneous Shut-In Pressure (ISIP)

Bradenhead Psi:

Frac Flow Back: Fluid:

Gas:

Comment:

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/11/2024

Annual Brhd Completed? Yes

Last Brhd Test Results

Initial Surf Csg Pressure: 0

Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506666	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815883