

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/04/2024

Document Number:

699506667**FIELD INSPECTION FORM**

Loc ID 447013	Inspector Name: MEDINA, JUSTIN	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 4 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
<b>Operator Information:</b> ECMC Operator Number: <u>69175</u> Name of Operator: <u>PDC ENERGY INC</u> Address: <u>1099 18TH STREET SUITE 1500</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

**Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447001	WELL	PR	08/25/2020	OW	123-43438	Dittmer KE 20-039HC	PR
447004	WELL	PR	12/01/2018	OW	123-43441	Dittmer KE 20-024HN	PR
447005	WELL	PR	11/19/2018	OW	123-43442	Dittmer KE 29-032HC	PR
447007	WELL	PR	01/01/2023	OW	123-43444	Dittmer KE 20-026HN	PR
447008	WELL	PR	01/01/2023	OW	123-43445	Dittmer KE 20-029HN	PR
447009	WELL	PR	11/15/2018	OW	123-43446	Dittmer KE 20-034HN	PR
447010	WELL	PR	11/24/2018	OW	123-43447	Dittmer KE 20-037HC	PR
447011	WELL	PR	01/01/2023	OW	123-43448	Dittmer KE 20-029HC	PR
447014	WELL	PR	12/01/2022	OW	123-43450	Dittmer KE 20-033HN	PR
447016	WELL	PR	04/11/2017	OW	123-43452	Dittmer KE 20-027HC	PR
447017	WELL	PR	10/01/2019	OW	123-43453	Dittmer KE 20-031HN	PR
447018	WELL	PR	11/08/2018	OW	123-43454	Dittmer KE 20-034HC	PR
447019	WELL	PR	12/01/2018	OW	123-43455	Dittmer KE 20-028HN	PR
447020	WELL	PR	11/16/2018	OW	123-43456	Dittmer KE 20-032HN	PR
447021	WELL	PR	04/14/2017	OW	123-43457	Dittmer KE 20-027HN	PR
447022	WELL	PR	11/10/2018	OW	123-43458	Dittmer KE 20-038HN	PR
447023	WELL	PR	11/15/2018	OW	123-43459	Dittmer KE 20-037HN	PR
447024	WELL	PR	11/27/2018	OW	123-43460	Dittmer KE 20-035HN	PR
447025	WELL	PR	04/01/2017	OW	123-43461	Dittmer KE 20-024HC	PR

**General Comment:**[Workover rig inspection](#)

Location				
Overall Good: <input checked="" type="checkbox"/>				
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:			Date:	
Flaring:				
Type				
Comment:				
Corrective Action:			Date:	

Inspected Facilities					
Facility ID: 447001	Type: WELL	API Number: 123-43438	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447004	Type: WELL	API Number: 123-43441	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447005	Type: WELL	API Number: 123-43442	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447007	Type: WELL	API Number: 123-43444	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447008	Type: WELL	API Number: 123-43445	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447009	Type: WELL	API Number: 123-43446	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447010	Type: WELL	API Number: 123-43447	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447011	Type: WELL	API Number: 123-43448	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447014	Type: WELL	API Number: 123-43450	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447016	Type: WELL	API Number: 123-43452	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447017	Type: WELL	API Number: 123-43453	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447018	Type: WELL	API Number: 123-43454	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447019	Type: WELL	API Number: 123-43455	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447020	Type: WELL	API Number: 123-43456	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447021	Type: WELL	API Number: 123-43457	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					
Facility ID: 447022	Type: WELL	API Number: 123-43458	Status: PR	Insp. Status: PR	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12					

Inspector Name: MEDINA, JUSTIN

Facility ID:	447023	Type:	WELL	API Number:	123-43459	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	447024	Type:	WELL	API Number:	123-43460	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID:	447025	Type:	WELL	API Number:	123-43461	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

#### Producing Well

Comment:			
Corrective Action:			Date:

#### Workover

Comment:	At time of inspection rig crew was in process of laying down tubing, Company representative informed me that they were in process of POOH to do a MIT on the well. EMI machine was used to scan tubing as rig crew POOH.		
Corrective Action:			Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

#### ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/04/2024

#### Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506668	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815884">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815884</a>