

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/05/2024

Document Number:

699506669**FIELD INSPECTION FORM**Loc ID 486772 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487189	WELL	DG	09/03/2024		001-10589	BIJOU 3-65 21-22-23 2BH	WO
487190	WELL	DG	09/01/2024		001-10590	BIJOU 3-65 21-22-23 1BH	WO
487191	WELL	DG	09/02/2024		001-10591	BIJOU 3-65 21-22-23 2AH	WO
487192	WELL	DG	08/31/2024		001-10592	BIJOU 3-65 21-22-23 1AH	WO
487193	WELL	DG	09/05/2024		001-10593	BIJOU 3-65 19-24 3BH	WO
487194	WELL	DG	08/31/2024		001-10594	BIJOU 3-65 20-19-24 2BH	WO
487195	WELL	DG	09/04/2024		001-10595	BIJOU 3-65 19-24 3AH	WO
487196	WELL	DG	08/28/2024		001-10596	BIJOU 3-65 20-19-24 1AH	WO
487197	WELL	DG	09/05/2024		001-10597	BIJOU 3-65 19-24 4AH	WO
487198	WELL	DG	08/30/2024		001-10598	BIJOU 3-65 20-19-24 2AH	WO
487199	WELL	DG	09/06/2024		001-10599	BIJOU 3-65 19-24 4BH	WO
487200	WELL	DG	08/29/2024		001-10600	BIJOU 3-65 20-19-24 1BH	WO

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					
Corrective Action:				Date: _____	
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:				Date:	
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities				
Facility ID:	487189	Type:	WELL	API Number: 001-10589 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487190	Type:	WELL	API Number: 001-10590 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487191	Type:	WELL	API Number: 001-10591 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487192	Type:	WELL	API Number: 001-10592 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487193	Type:	WELL	API Number: 001-10593 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487194	Type:	WELL	API Number: 001-10594 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487195	Type:	WELL	API Number: 001-10595 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487196	Type:	WELL	API Number: 001-10596 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487197	Type:	WELL	API Number: 001-10597 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487198	Type:	WELL	API Number: 001-10598 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487199	Type:	WELL	API Number: 001-10599 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	487200	Type:	WELL	API Number: 001-10600 Status: DG Insp. Status: WO
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Well Stimulation				
Stimulation Company: Liberty		Stimulation Type: HYDRAULIC FRAC		
Observation:		Other:		
Maximum Casing Recorded: PSI		Tubing:		
Surface:		Intermediate:		
Production:		Instantaneous Shut-In Pressure (ISIP)		
Bradenhead Psi:		Frac Flow Back: Fluid: Gas:		
Comment: At time of inspection site was being prepared for Hydraulic fracture. Equipment was in process of being set up on location.				
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

ECMC Comments		
Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/05/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506670	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815885