

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/05/2024

Document Number:

699506671

FIELD INSPECTION FORMLoc ID 487289 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
488243	WELL	DG	11/26/2024		001-10613	INVICTA 3-65 30-26 3H	DG
488244	WELL	DG	11/27/2024		001-10614	INVICTA 3-65 30-26 2H	DG
488245	WELL	DG	11/24/2024		001-10615	INVICTA 3-65 30-26 5H	DG
488246	WELL	DG	11/28/2024		001-10616	INVICTA 3-65 30-26 1H	DG
488247	WELL	DG	11/25/2024		001-10617	INVICTA 3-65 30-26 4H	DG
488248	WELL	DG	11/21/2024		001-10618	INVICTA 3-65 30-26 8H	DG
488249	WELL	DG	11/23/2024		001-10619	INVICTA 3-65 30-26 6H	DG
488250	WELL	DG	11/22/2024		001-10620	INVICTA 3-65 30-26 7H	DG

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:					Date: _____
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:			Date:		
Flaring:					
Type					
Comment:					
Corrective Action:			Date:		

Inspected Facilities

Facility ID: 488243	Type: WELL	API Number: 001-10613	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488244	Type: WELL	API Number: 001-10614	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488245	Type: WELL	API Number: 001-10615	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488246	Type: WELL	API Number: 001-10616	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488247	Type: WELL	API Number: 001-10617	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488248	Type: WELL	API Number: 001-10618	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488249	Type: WELL	API Number: 001-10619	Status: DG	Insp. Status: DG
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 488250	Type: WELL	API Number: 001-10620	Status: DG	Insp. Status: DG

Well Drilling

Rig: Rig Name: Patterson 572 Pusher/Rig Manager: _____
 Permit Posted: SATISFACTORY Access Sign: SATISFACTORY

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: At time of inspection rig crew was in process of moving rig to next well.

Corrective Action: _____ **Date:** _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with ECMC rules. At time of inspection weather conditions were cold, calm, clear.	medinaj	12/05/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506672	inspection pictures	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815886