

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SE14N (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024



Photo # 0178 Entrance to location



Photo # 0189 Location

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SE1W (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024




Photo # 0179 Location



Photo # 0183 Location



## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SE14N (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024



Photo # 0188 Location



Photo # 0216 SE corner of location

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SENW (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024



Photo # 0217 SW corner of location



Photo # 0218 NE corner of location



## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SEW (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024



**Photo # 0203 Flow line heating insulation open ended/wildlife hazard available for entry by wildlife**



**Photo # 0209 Wildlife protection for Methanol tank containment needs maintenance/netting is damaged and open to wildlife**

## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SEW (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024




Photo # 0192 Capacity on condensate tank is weathered and becoming illegible



Photo # 0200 Debris



## Inspection Photos

Location: QB ENERGY PUCKETT-67S97W/1SEW (PUCKETT 22B-1 PAD)

Location ID: 324253

Date: 12/3/2024




Photo # 0214 Debris



Photo # 0206 Some information on methanol tank is peeling and becoming illegible