

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2024

Submitted Date:

12/08/2024

Document Number:

708905199

FIELD INSPECTION FORM

 Loc ID 324247 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635
Findings:
 18 Number of Comments
 0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269870	WELL	PR	03/31/2004	GW	045-09418	LAST DANCE 9-3	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 12/06/2024 at approximately 13:43 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC LAST DANCE 9-3 Pad.
 Location # 324247 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear Habitat areas.
 Location is approximately 21 yards from Multa Trina Ditch.
 While there, I observed normal production operations.

[This is a summary of inspection report.](#)

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - ECD is disconnected & not in use The storage or placement of equipment and supplies not necessary for use on location is prohibited.		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	SEPARATOR		
Comment:	Cattle panels		
Corrective Action:			Date:
Type	WELLHEAD		

Comment:	Cattle panels		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Cattle panels		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Cattle panels		
Corrective Action:			Date:

Equipment:				corrective date
Type: Horizontal Heated Separator	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:	Well on plunger lift			
Corrective Action:				Date:
Type: Bradenhead	# 1			
Comment:	Taylor plug located on bradenhead, bradenhead valve is accessible			
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	ECD is disconnected & not in use/unused equipment			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	200 BBLs	HEATED STEEL AST		,
Comment:	Tanks not equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			

Comment:	Centralized containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 269870 Type: WELL API Number: 045-09418 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Rip Rap						BMP may need maintenance in near future
Berms		Compaction				
		Gravel				Sparse to none in sections
		Ditches				
		Culverts				

Comment: [Rip Rap Run showing some signs of erosion/disrepair & may need maintenance in near future \(SE corner of location near tank battery containment\)](#)
[Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping & Stormwater for comments	smelserw	12/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905200	Inspection 708905199 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815930
708905201	Inspection 708905199 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6815931