

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0245 Entrance to location




Photo # 0256 Location

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Dec 3, 2024 at 3:36:31 PM
+39.533009, -108.163345 +4.72m

Photo # 0246 Location



Dec 3, 2024 at 3:38:43 PM
+39.533084, -108.163222 +5.20m

Photo # 0249 Location

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0255 Location



Photo # 0279 SE corner of location

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0280 SW corner of location



Photo # 0265 Loose barbed wire fencing/wildlife hazard

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0267 Loose barbed wire fencing/wildlife hazard



Photo # 0270 Wildlife protection for Methanol tank containment needs maintenance/netting is damaged and open to wildlife

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0273 Wildlife protection for Methanol tank containment needs maintenance/netting is damaged and open to wildlife



Photo # 0257 Some information on condensate tank is peeling

Inspection Photos

Location: QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696)

Location ID: 335776

Date: 12/3/2024



Photo # 0269 Capacity label is peeling on methanol tank