

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2024

Submitted Date:

12/08/2024

Document Number:

713400519

FIELD INSPECTION FORM

 Loc ID: 335776
 Inspector Name: Popejoy, Dusty
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 25 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
 ECMC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269986	WELL	PR	03/01/2019	GW	045-09437	CHEVRON/TEXACO 44C-12D	PR
269987	WELL	PR	03/01/2019	GW	045-09433	CHEVRON/TEXACO 33C-12D	PR
269988	WELL	PR	03/01/2019	GW	045-09434	CHEVRON/TEXACO 43C-12D	PR
269989	WELL	PR	07/01/2024	GW	045-09436	CHEVRON/TEXACO 41C-13D	PR

General Comment:[CECMC Inspection Report Summary](#)

On 12/3/2024 at approximately 15:35 hours, Compliance Inspector Dusty Popejoy conducted a Follow up inspection at QB ENERGY CHEVRON/TEXACO-66S97W/12SESE (GARDEN GULCH 5 696) at Location ID #335776 in Garfield County, Colorado.

Please refer to inspection 713400228 conducted on 08/1/2024, 3 of 4 corrective actions have been completed. Loose barbed wire fencing/wildlife hazard has not been completed and CA date remains 08/1/2024

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

- Housekeeping - Loose barbed wire fencing/wildlife hazard with a CA date of 08/1/2024
- Housekeeping - Wildlife protection for Methanol tank containment needs maintenance/netting is damaged and open to wildlife with a CA date of 12/15/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
	Type	Access	
	comment:	Access	
	Corrective Action		Date:

Overall Good:

Signs/Marker:			
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:		
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:	Some information on condensate tank is peeling and becoming illegible, refer to photos Capacity label is peeling on methanol tank, refer to photos	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	970-285-2615/911	
	Corrective Action:		Date: _____

Good Housekeeping:			
	Type	OTHER	
	Comment:	Loose barbed wire fencing/wildlife hazard, refer to photos.	
	Corrective Action:	Comply with CECMC wildlife rules	Date: 08/01/2024
	Type	OTHER	
	Comment:	Wildlife protection for Methanol tank containment needs maintenance/netting is damaged and open to wildlife, refer to photos	
	Corrective Action:	Comply with CECMC wildlife rules	Date: 12/15/2024

Overall Good:

Spills:			
	Type	Area	Volume
	In Containment:	No	
	Comment:	<input style="width: 100%;" type="text"/>	
	<input type="checkbox"/> Multiple Spills and Releases?		

Fencing/:			
Type	OTHER		
Comment:	Nitrogen tank - Pipe rail fencing		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire fencing/Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Livestock panels around methanol tank and containment		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Thermoelectric generator		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol tank/Pump		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Nitrogen tank		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:	Tank equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 269986 Type: WELL API Number: 045-09437 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269987 Type: WELL API Number: 045-09433 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269988 Type: WELL API Number: 045-09434 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 269989 Type: WELL API Number: 045-09436 Status: PR Insp. Status: PR

Producing Well

Comment: Producing well

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Ditches						
		Berms				
Compaction						
		Ditches				
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for corrective actions and Signs/Marker for comments.	popejoyd	12/08/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400520	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6816117