

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2565 From entrance to location



Photo # 2566 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2567 Location



Photo # 2568 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2569 Location



Photo # 2570 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2571 Location



Photo # 2572 Location




## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



**Photo # 2573 Blowdown tank label weathered & illegible /does not comply with CECMC rules. Additionally capacity on tank label is also incorrect**



**Photo # 2574 Capacity on tank label for blowdown tank is incorrect/does not comply with CECMC rules**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



Photo # 2575 Correct tank capacity



Photo # 2576 Secondary containment insufficient/does not comply with CECMC rules





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695




Photo # 2577 Tank label weathered & damaged




Photo # 2578 Tank label weathered & damaged

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



**Photo # 2579 Unused hose in secondary containment**



**Photo # 2580 Unused hose & small amount of debris in secondary containment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



**Photo # 2581 CIRCLE B LAND 14C-35-692 well bradenhead line connected to blowdown tank**



**Photo # 2582 CIRCLE B LAND 14C-35-692 well bradenhead line connected to blowdown tank**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 24B-35-692 Pad

Location ID: 334695



**Photo # 2583 CIRCLE B LAND 14C-35-692 well bradenhead  
line connected to blowdown tank**