

Inspection Photos


Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Dec 5, 2024 at 2:36:22 PM
+39.463689,-108.065123 ±2.58m
Parachute



Dec 5, 2024 at 2:54:53 PM
+39.463720,-108.064800 ±3.25m
Parachute

TEP Rocky Mountain LLC

970-285-9377

GM 14-1 PRODUCTION FACILITY

GM 14-1 PAD	API
SWSW SEC 1/T7S/R96W	
GM 14-1	05-045-07418
GM 314-1	05-045-09500
GM 413-1	05-045-10244

GM 250-1 PAD	API
NWSW SEC 1/T7S/R96W	
GM 250-1	05-045-07443

NWSW SEC 1/T7S/R96W
GARFIELD COUNTY, CO
EMS 911
ACCESS FROM: CR. 215

Photo # 0305 Entrance to location

Photo # 0332 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0306 Location



Photo # 0319 Location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0330 Location



Photo # 0341 NE corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0342 SE corner of location



Photo # 0348 NW corner of location

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0326 Open ended piping/wildlife hazard/ available for entry by wildlife




Photo # 0329 Open ended piping/wildlife hazard/ available for entry by wildlife

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0335 Suspected leaks on production tank/tank appears to lack integrity



Photo # 0336 Suspected leaks on production tank/tank appears to lack integrity

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0337 Suspected leaks on production tank/tank appears to lack integrity



Photo # 0313 Wellhead signs are weathered & cracked and becoming illegible

Inspection Photos

Location: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W/1NWSW (GM 14-1 PAD)

Location ID: 334925

Date: 12/5/2024



Photo # 0317 Wellhead signs are weathered & cracked and becoming illegible

