

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2024

Submitted Date:

12/09/2024

Document Number:

709100457

FIELD INSPECTION FORM

Loc ID 312314 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Krystal Heibel		krystal.heibel@state.co.us	
Fritzler, Gene	(970) 768-0845	gfritzler@bresnan.net	All Inspections
Kyle Waggoner		kyle.waggoner@state.co.us	
Fritzler, Steve	(970) 867-9388	sfritzler@friesources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221192	WELL	PR	02/10/2006	OW	075-09318	FEHRINGER 1	EI
312314	LOCATION	AC			-	FEHRINGER-612N52W 28SWNE	EI

General Comment:

[This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions.](#)

Location			
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	No signage on polytank / Install sign to comply with Rule 605.h.(3).		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type			
Comment:	Plank of wood observed and weeds present / Comply with Rule 606		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Crude Oil	Pump Jack		
Comment:	Hydrocarbon stained soil observed within pumpjack shed and gear box. FIR Resolution Form (Doc# 404012377) documents the Operator Comment to CA# 177542 that "All E&P waste near pumping unit was removed and stockpiled for disposal." from August 8, 2023. EMCM Staff documents impacted soil staining within the pumpjack shed and below the gearbox		
Corrective Action:	Report spill or release of E&P waste via a Form 19 and contact ECMC EPS Staff (krystal.heibel@state.co.us) per Rule 912.b. Operator shall collect confirmation soil samples as described in the Rule 915.e.(2) Guidance Document. Operator will analyze soil samples for TPH (C6-C36), Table 915-1 Organic Compounds in Soil, Table 915-1 metals, and Table 915-1 Soil Suitability for Reclamation (Electrical conductivity, Sodium adsorption ratio, and pH by saturated paste method, boron (hot water soluble)).		Date: <u>12/09/2024</u>
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	#		corrective date
Comment:	Multiple valves are not securely fastened. / Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		
Corrective Action:			Date:
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 221192 Type: WELL API Number: 075-09318 Status: PR Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 312314 Type: LOCATION API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
709100458	Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817228