

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/09/2024

Document Number:

698602700**FIELD INSPECTION FORM**Loc ID 303242 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**18 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------------|---------|
| Pesicka, Conor | | conor.pesicka@state.co.us | |
| Dolezal, Pat | 970-332-3585 | pat.dolezal@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 252736 | WELL | PR | 02/09/1988 | GW | 125-06612 | SALVADOR 2-5 | PR |

General Comment:Routine Inspection.

Location

| | | | |
|--------------------|---|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Two track off maintained County Road. Active agricultural cropland with seasonal access to well location. | | |
| Corrective Action | | Date: | |

Overall Good: ☐

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Well sign at wellhead location. | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Sign at remote gathering location is inaccurate and reflects Salvador 6-5 for API #125-06612. | | |
| Corrective Action: | Install sign to comply with Rule 605.a. | Date: | 01/09/2025 |

Emergency Contact Number:

Comment: Emergency contact information posted on well sign.

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|--|
| Type | DEBRIS | | |
| Comment: | Pit located at remote gathering location contains dried vegetation debris. | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|---|-------|--|
| Type | OTHER | | |
| Comment: | Stock panel fencing around surface equipment at remote gas metering location. | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|--|-------|-----------------|
| Type: Other | # 1 | | corrective date |
| Comment: | Shared Remote Gas Meter Shed. | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | Flowline mounted separator box with small vertical separator inside. | | |
| Corrective Action: | | Date: | |
| Type: Dehydrator | # 1 | | |
| Comment: | Dehydrator on gas meter run inlet. | | |

| | | | |
|---------------------------|---|-------|--|
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | Bradenhead plumbed to surface. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Remote Gas Meter Run located on CR 54 & CR Q. Digital Gas Meter Run. Meter Calibration/Test Log dated 3-18-24. Well Inlet Valve open. Gas Outlet Valve open. Calibration log reflects Salvador 6-5 for API #125-06612. Lease name should be Salvador 2-5, API 125-06612 based on COGIS Scout Card. CA in FIR Sign/Marker Section. | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Wellhead. Casing production. Rods removed and tubing in the wellbore. Tubing valve open. Casing valve not connected. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| Inspected Facilities | | | | | | | | | |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 252736 | Type: | WELL | API Number: | 125-06612 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Rods removed and tubing in wellbore. Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 9/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR. | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: 15Width: 15**Lining:**

Liner Type:

Liner Condition:

None.

Comment:

This discharge pit is located at remote gathering location outside the fenced in shared meter shed for the Salvador 5-5 and Salvador 2-5 (sign on meter shed reflects incorrectly the Salvador 6-5) on CR 54 & CR Q. The pit does not appear to be the permitted/related Pit 107851 in COGIS based on location. Discharge flowline originates out of flowline mounted separator at remote gathering location and discharges to pit. Pit berms are worn and evidence of dead/dried vegetation on them. There is trapped debris inside pit and on berms.

Corrective Action

Submit an eForm 15 Pit Report to update ECMC records with current information to comply with Rule 908.c. Comply with Rule 909.

Date: 01/09/2025**Fencing:**

Fencing Type:

Fencing Condition:

Comment: None.

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment: None.

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 698602732 | Inspection photos. | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817478 |