

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2024

Submitted Date:

12/09/2024

Document Number:

713400527

## FIELD INSPECTION FORM

 Loc ID: 323790  
 Inspector Name: Popejoy, Dusty  
 On-Site Inspection:   
 2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Operator Information:**
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Contact Information:**

| Contact Name    | Phone | Email                              | Comment |
|-----------------|-------|------------------------------------|---------|
| Kellerby, Shaun |       | shaun.kellerby@state.co.us         |         |
| , TEP           |       | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type         | Status | Status Date | Well Class | API Num | Facility Name       | Insp Status |
|-------------|--------------|--------|-------------|------------|---------|---------------------|-------------|
| 456910      | Domestic Tap | AC     | 08/28/2018  |            | -       | Domestic Tap 34NENW | AC          |

**General Comment:****CECMC Inspection Report Summary**

On 12/5/2024 at approximately 14:40 hours, Compliance Inspector Dusty Popejoy conducted a follow up domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap 34NENW at Location ID #323790 Facility #456910 in Garfield County, Colorado.

Please refer to inspection 708903759 conducted on 05/9/2024, previous corrective action has not been completed & CA date remains 12/26/2023

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Equipment - PRV vent line does not comply with CECMC pressure safety device rules with a CA date of 12/26/2023

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           | Access |       |  |
| Corrective ActionL |        | Date: |  |

Overall Good:

|                                  |  |
|----------------------------------|--|
| <b>Emergency Contact Number:</b> |  |
| Comment:                         | <input style="width: 80%;" type="text"/> |
| Corrective Action:               | <input style="width: 80%;" type="text"/> |
|                                  | Date: _____                              |

Overall Good:

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |   |  |       |                 |
|--------------------|---|--|-------|-----------------|
| <b>Equipment:</b>  |   |  |       | corrective date |
| Type: Other        | # 1   |  |       |                 |
| Comment:           | PRV vent line does not comply with CECMC pressure safety device rules |  |       |                 |
| Corrective Action: | Comply with CECMC pressure safety device rules                        |  | Date: | 12/26/2023      |
| Type: Other        | # 1   |  |       |                 |
| Comment:           | Domestic tap  |  |       |                 |
| Corrective Action: |   |  | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 456910 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following regulator there's a fluid knock out equipped with a PRV, following the knock out there's a little Joe regulator & after the regulator there's an in line odorizer. Fittings appear to be adequate.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <span style="color: blue;">Please refer to Equipment for corrective action.</span> | popejoyd | 12/09/2024 |
| <span style="color: blue;">Domestic tap inspection only</span>                     |          |            |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 713400528    | Inspection Photos | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817676">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817676</a> |