

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/05/2024

Submitted Date:

12/09/2024

Document Number:

713400531

FIELD INSPECTION FORM

Loc ID 323967 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467556	Domestic Tap	AC	09/16/2019		-	Domestic Tap 34NWSW	AC

General Comment:

[CECMC Inspection Report Summary](#)

On 12/5/2024 at approximately 17:02 hours, Compliance Inspector Dusty Popejoy conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap34NWSW Location #323967 Facility #467556 Garfield County, Colorado.

While there, I observed the domestic tap is derived from TEP sales line.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 80%;" type="text"/>
Corrective Action:	<input style="width: 80%;" type="text"/>
	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:				corrective date
Type: Other	# 1			
Comment:	Domestic tap			
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Domestic tap - pipe rail fence			
Corrective Action:			Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 467556 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: While there, I observed the domestic tap is derived from TEP's sales line. The pressure is regulated by a big Joe regulator. Following the big joe there's a little Joe regulator. Following the little joe there's a fluid knock out equipped with a PRV, following the knock out there's an in line odorizer. Fittings appear to be adequately sized

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Domestic tap inspection only</u>	popejoyd	12/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400532	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817839