

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 12/6/2024



Location – Photo #05190



Location – Photo #05194



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 12/6/2024



Location – Photo #05192



Open Wellhead Cellar/No Wildlife Egress – Photo #05191

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 12/6/2024



Insufficient Erosion Control – Photo #05195



Sediment Transport Off Site – Photo #05198

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 324239

Date: 12/6/2024



Sediment Transport Off Site – Photo #05197