

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 12/6/2024



Location – Photo #05201



Location – Photo #05193

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 12/6/2024



Location – Photo #05194

Location – Photo #05192

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 12/6/2024



Insufficient Erosion Control/Degradation – Photo #05205



Insufficient Erosion Control/Degradation – Photo #05206

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/27SWSE

Location ID: 335398

Date: 12/6/2024



Insufficient Erosion Control/Degradation – Photo #05207



Open Wellhead Cellar/No Wildlife Egress – Photo #05202