

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2024

Submitted Date:

12/03/2024

Document Number:

718100022**FIELD INSPECTION FORM**Loc ID 334427 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Laramie		cogccnotifications@laramie-energy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
334427	LOCATION	AC			-	Piceance 28-05 Pad	RI

General Comment:

On 11/12/2024, Western Reclamation Work Lead Trujillo conducted an inspection at Laramie Energy LLC's Piceance 28-05 Pad Location in Mesa County, Colorado.

This inspection is a follow-up to #696206341 to document compliance with the following corrective actions:
-Interim Reclamation / Stormwater

This inspection is also in response to FIRR #403969396 stating CAs have been completed; it was observed in this inspection that the CAs appear to have been resolved.

The following new compliance issues were observed during this inspection:
-Stormwater- Stabilization/tracking

Due to technical difficulties, inspector was unable to submit this inspection report within an appropriate timeframe- Operator was provided notice of the compliance issues and corrective action requirements in an email on 11/15/2024.

Refer to the Stormwater sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Location entrance		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-981-6191 / 911

Corrective Action: _____ Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	See inspection #696206341 for comments regarding weeds.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	334427	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND, RECREATIONAL

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING

Comment

Corrective Action Date

1002b. SOIL REMOVAL AND

Comment

Corrective Action Date

1002c. PROTECTION OF SOILS

Comment

Corrective Action Date

1002E. SURFACE DISTURBANCE MINIMIZATION

Comment

Corrective Action Date

1003a. Waste and Debris removed?

Comment

Corrective Action Date

Unused or unneeded equipment onsite?

Comment

Corrective Action Date

Pit, cellars, rat holes and other bores closed?

Comment

Corrective Action Date

Guy line anchors marked?

Comment

Corrective Action Date

1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment [See "COGCC Comments" at the end of this report.](#)

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND, RECREATIONAL _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

It was observed in this inspection that BMPs to stabilize the working pad surface, as well as to minimize tracking and sediment transport are in disrepair; the working pad surface lacks stabilization and tracking is evident.

Corrective Action:

Comply with Rule 1002.f

Date:

11/22/2024

Pits:

☐ NO SURFACE INDICATION OF PIT

ECMC Comments		
Comment	User	Date
<div>RECLAMATION COMMENT</div> <p>Inspection #696206341 observed that the slopes on the south/southeast end of the Location are predominantly bare soils; slopes lack stabilization and erosion degradation is evident. Inspection required additional reclamation and stabilization efforts within these areas of the Location.</p> <p>Operator submitted FIRR #403969396, stating “Erosion and rills raked with seeding and wattles added to slope.”</p> <p>Limited inspection due to snow cover though work at the slopes is evident- surface roughening (tracking) appears to have been implemented. Erosion logs per Operator's comment was not observed. It is being noted that tracking is a temporary erosion control measure that should be used in conjunction with a secondary erosion control measure per good engineering practices.</p> <p>This CA is being considered resolved at this time. Ensure the temporary BMPs to stabilize the slopes are maintained in proper functioning condition until long term stabilization, such as uniform perennial vegetative cover, has been achieved. If it is determined that a specific BMP is insufficient to minimize erosion, degradation and/or sediment transport, or cannot be implemented per installation specification, or maintained in effective operating condition, then alternative BMPs that are better suited to meet the site's conditions should be considered and applied, or used in conjunction.</p>	trujilloam	12/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404014107	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6809690
718100023	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6809682