

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2024

Submitted Date:

12/10/2024

Document Number:

707603425

FIELD INSPECTION FORM

Loc ID: 306224 Inspector Name: Evins, Bret On-Site Inspection: 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286646	WELL	PR	04/01/2022	OW	123-24252	MILE-HI SHEEP 8-35	WK

General Comment:

This is a **PLUGGED & ABANDONED WELL / WORKOVER** inspection.
Well(s): 1: Workover | WK.
Plugging Operations: Kill well.
Battery: Inactive. Shut-down.
Inactive Battery SE corner GPS coordinates: 40.496587 / -104.581834
Well GPS coordinates: 0.496930 / -104.579830

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Jobsite entrance & safety signage posted.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	<input style="width: 500px;" type="text"/>	
Corrective Action:	<input style="width: 500px;" type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type:	Plunger Lift	# 0	
Comment:	Workover WK. Equipment removed.		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 286646 Type: WELL API Number: 123-24252 Status: PR Insp. Status: WK

BradenHead

Date of Last Brhd Test: 02/26/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Workover

Comment: 2024/12/09:
Plugging Operations: Kill well.
2024/12/09: JSA attached as photo to this report.

Workover Contractor: Axis Energy Services Rig #714.
Cement Contractor: Axis Energy Services.

Reference:
Form 6N on file. Notice of Intent to Abandon date: 09/23/2024. Approved.
Form 42 on file. Notice of MIRU. Start Date: 12/04/2024. Approved.
Form 42 on file. Notice of Plugging Operations. Start Date: 12/04/2024. Approved.

CTL, HSM AND REVIEW SWC ON RIG MOBILIZATION (WSEA 2-A). DROVE RIG FROM UPV 13-1114 -SPOT IN RIG. HSM (WSEA 2-B) AND REVIEW SWC ON MECHANICAL LIFTING AND RIGGING-PERFORM DROPS INSPECTION-RIG UP RIG AND EQUIPMENT. STUMP TEST BOP AND SRF EQUIPMENT (WSEA8-A) LOW 250 PSI/ HIGH 2000 PSI. CHECK IWP = 650 SITP/ 650 SICP/ 0 SIBHP. PERFORM 30 MIN BRHD TEST- NO CHANGE ON TBG/ CSG PRESSURE. BULL HEAD 70 BBLS DN CSG AND 30 BBLS DN TBG-ROLL HOLE UNTIL FREE OF OIL. INSURE WELL STATIC 15 MIN FLOW TEST (WSEA 10-A). ND WH/ NU BOP-RU WORK FLOOR. TEST BOP CONNECTION LOW/HIGH =GOOD. POOH TO DERRICK W/ 78 JTS 2-3/8" TBG. POOH LD 151 JTS 2-3/8" TBG, SN/NC. SWIFD-DRAIN PUMP AND LINES-CREW TO YARD.

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 12/09/2024 at approximately 13:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: MILE-HI SHEEP-66N64W/8SWSW Location ID: 306224 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Mostly Cloudy, damp from prior storm.</p> <p>While there, I observed: Well(s): 1: Workover WK. Plugging Operations: Kill well. Battery: Inactive. Shut-down. Inactive Battery SE corner GPS coordinates: 40.496930 / -104.579830 Well GPS coordinates: 40.496587 / -104.581834</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	12/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603427	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6818895