

Inspection Photos

API: 071-09013

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. There is insufficient BMP's installed along the roadside to prevent erosion.



Inspection Photos



Photo 2. The erosion along the road side has insufficient BMP's to prevent continued erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09013 | Date: 12/9/2024

Inspection Photos




Photo 3. Facing toward the wellsite. There was a water leak at the wellhead which flowed to the northwest side of the location. Operator was immediately notified.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-09013 | Date: 12/9/2024

Inspection Photos



Photo 4. The water was leak out steadily from the wellhead which prompted immediate notification. Operator was seen traveling to the site for repair.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing toward the northwest side where erosion had occurred. This area was previously vegetated but soils were pushed to fill in the erosion. The hydro-mulch applied was clumpy with uneven coverage.



Inspection Photos



Photo 6. There is erosion already occurring where soils were pushed out to fill in the previously observed erosion channel.



Inspection Photos



Photo 7. Facing southwest at the location. The loose soils pushed out to this area are susceptible to erosion. A new erosion channel has already developed.

