

Inspection Photos
Location Name: QB Energy LAZIER (P23B) Pad
Location #: 335320



Photo # 2904 From entrance to location




Photo # 2905 Location

Inspection Photos
Location Name: QB Energy LAZIER (P23B) Pad
Location #: 335320



Photo # 2906 Location



Photo # 2907 Location



Location #: 335320

Dec 10, 2024 at 2:48:31 PM
CO

Photo # 2909 Battery sign not located at battery

Inspection Photos
Location Name: QB Energy LAZIER (P23B) Pad
Location #: 335320



Photo # 2910 PRV vent line does not comply with CECMC pressure safety device rules




Photo # 2911 PRV vent line does not comply with CECMC pressure safety device rules