

Inspection Photos

Loc: 307766

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 307766 | Date: 12/9/2024

Inspection Photos



Photo 2. The erosion channels along the fill slope have been filled in with rock.



Inspection Photos



Photo 3. The fill slope was filled in with rock and some hydromulch was spread along area of the red arrow.



Inspection Photos



Photo 4. Northeast side of the location facing west. The erosion channels were filled in with rock. Stormwater will find least resistant pathway would could create erosion toward area of red arrow.



Inspection Photos



Photo 5. Facing toward the cu slope. There is erosion along the cut slope that needs to be regraded and seeded.



Inspection Photos



Photo 6. 2024 aerial imagery of the location shows unused areas at the north side of the location will need to be revegetated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 307766 | Date: 12/9/2024