

Inspection Photos

API: 071-06970

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northwest along the access road. The culvert has been cleaned out.



Inspection Photos



Photo 2. Facing northwest along the road. The culvert has been cleaned out and road base was added to promote drainage off the road.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing east toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:071-06970 | Date: 12/9/2024

Inspection Photos



Photo 4. There is ice build up of a slight water leak at the wellhead.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing toward the cut slope which has been tracked for temporary stabilization.



Inspection Photos



Photo 6. Facing down toward the cut slope. There was some sparse hydromulch spread. It appears work is still in process however hydromulch must be uniformly spread with complete coverage for proper stabilization.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06970 | Date: 12/9/2024

Inspection Photos



Photo 7. Facing toward the top portion of the cut slope.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources