

Inspection Photos

API: 071-09051

Operator: WAPITI OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access roads. More BMP's need to be installed up along the road to slow down or divert stormwater off the road..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 12/9/2024

Inspection Photos



Photo 2. Facing There are some rock check dams installed but stormwater has already eroded around the out side.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 3. The culvert is cleaned out and this check dams has held back a lot of sediment. The check dam will need to be cleaned out and sediment control further up the road should be installed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 12/9/2024

Inspection Photos



Photo 4. The green wattles were installed at the culvert outlet which has already filled in with sediment. The wattles will need to be cleaned out and sediment control further up the road should be installed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 12/9/2024

Inspection Photos



Photo 5. Facing southeast toward the wellsite.

