

Inspection Photos

API: 071-06299

Operator: OGRIS OPERATING LLC

Inspection Date: 12/9/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road. There is erosion along the road that needs to be repaired.



Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. The erosion gully along the cut slope has been repaired.



Inspection Photos



Photo 4. There is a run-of swale above the location that has been graded to promote stormwater away from the cut slope.



Inspection Photos



Photo 5. Facing toward the erosion repair. It appears the excavator teeth were dragged downhill along the slope which will promote erosion. Tracking or grading should be performed perpendicular to the slope to prevent erosion.

