

# Inspection Photos

12/10/2024

**Operator:** TEP ROCKY MOUNTAIN LLC #96850

**Location ID:** 383325

**Inspection Doc:** 718100100

Garfield County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



**Photo 1:** Limited inspection due to snow cover. Unable to find evidence that additional reclamation has been performed, and stabilization control measures installed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



**Photo 2:** Unused equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**


Department of Natural Resources



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



**Photo 3:** Knockout on the NW end of the Location. Leak detected at bottom valve resulting in gas being vented and fluids spilling onto the pad surface.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



**Photo 4:** Knockout on the NW end of the Location. Photo shows impacted soils due to spill. Photo also shows broken pieces of glass.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 383325



December 10, 2024

**Photo 5:** Pipe equipment used to support the pipeline between the tank battery and knockout has fallen over.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources