

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

718100096**FIELD INSPECTION FORM**Loc ID 335055 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
Longworth, Mike		mike.longworth@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	All Inspections
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335055	LOCATION	AC			-	CSF-67S91W 7SEW	RI

General Comment:

On 12/10/2024, Western Reclamation Work Lead Trujillo conducted an interim reclamation and stormwater inspection at TEP Rocky Mountain LLC's CSF-67S91W/7SEW Location in Garfield County, Colorado.

Location is Fed Surface / Fed Minerals.

This inspection is a follow-up to #696206116 and #701103784 to document compliance with the following corrective actions:

- Unmarked anchors
- Leak at wellhead.
- Unused equipment.
- Container Label
- Stained soils

Limited inspection due to snow cover.

It was observed in this inspection that the corrective actions related to the Leak, Label and Soil Staining have been resolved; corrective actions related to anchor marking requirements and unused equipment remain outstanding.

The following new compliance issues were observed during this inspection:

- Cellars at wells improperly covered.

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Label has been maintained. CA per inspection #696206116 has been resolved.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	<p>Inspection #701103784 observed multiple unused flowlines at the tank battery, separators and AL well CSF #12A-07-07-91. Inspection required Operator to apply OOSLAT, per Rule 1101.a.(3).C. and remove all unused equipment (unused flowlines) per Rule 606 by 8/31/2023.</p> <p>It was observed in this inspection that OOSLAT has been applied to risers, however equipment has not been removed per the CA.</p> <p>This CA has not been addressed and remains applicable. Including Integrity Engineer Tech and Compliance Inspector for notification purposes.</p>		
Corrective Action:	<p>CA Per inspection #701103784:</p> <p>Apply OOSLAT, per Rule 1101.a.(3).C. Remove all unused equipment (unused flowlines) per Rule 606.</p>	Date:	
Type	OTHER		
Comment:	It was observed in this inspection that grates at the wells do not properly cover the entire cellar, resulting in large gaps/holes.		
Corrective Action:	Install or repair required BMPs to ensure cellars are properly covered to comply with Rules 602.c and 902.b	Date:	12/18/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused pipe CA per #696206116 has been resolved.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: Spill CA, and Leak CA related to the CSF 31B-07-07-91 well has been resolved.

☐ Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	335055	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Fail

Comment

Inspection #696206116] observed anchors on the Location missing required marking, or markers were in disrepair. Inspection required Operator to comply with Rules 1003.a and 603.j by 9/13/2024.

Limited inspection due to snow cover, however markers were not observed within areas of the anchors. Additionally no Resolution has been submitted stating work to address the CAs have been performed pursuant to Rule 210.b

This CA has not been addressed and remains applicable.

Corrective Action

CA Per Inspection #696206116

Comply with Rule 1003.a and 603.j

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment [Limited inspection due to snow cover- see Inspection #696206116 for comments related to Interim Reclamation.](#)

Corrective Action _____ Date _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Limited inspection due to snow cover- No immediate stormwater concerns observed at time of inspection.

Corrective Action:

Date:

Pits:

☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100097	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821216