

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2024

Submitted Date:

12/11/2024

Document Number:

718100100

## FIELD INSPECTION FORM

 Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
 383325 \_\_\_\_\_ Trujillo, Aaron \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_
**Operator Information:**
 ECMC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: 1058 COUNTY ROAD 215  
 City: PARACHUTE State: CO Zip: 81635
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 7 Number of Comments  
 5 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Smelser, Wayne		wayne.smelser@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
383325	LOCATION	AC			-	GGU MILLER-66S91W 31SWSE	RI

**General Comment:**

On 12/10/2024, Western Reclamation Work Lead Trujillo conducted an inspection at TEP Rocky Mountain LLC's GGU MILLER-66S91W/31SWSE Location in Garfield County, Colorado.

Location is within High Priority Habitats- Elk Severe Winter Range; Mule deer Severe Winter Range; Mule Deer Winter Concentration Area.

This inspection is a follow-up to Inspection Nos. 696206130 and 707800227 to document compliance with the following corrective actions:  
 -Interim Reclamation  
 -Unused equipment

Limited inspection due to snow cover.

It was observed in this inspection that the corrective actions related to unused equipment and reclamation remain outstanding.

The following new compliance issues were observed during this inspection:  
 -Leak at the knock-out equipment / spill

Refer to the "Location" and "Reclamation" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	it was observed in this inspection that the pipe equipment used to support the line from the tank battery to the knock-out equipment on the west end of the Location has fallen over.		
Corrective Action:	Maintain support equipment. If equipment is no longer necessary it should be removed pursuant to 606 requirements.	Date:	12/26/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused drag equipment documented in Inspection #696206130 has been removed. This CA has been resolved.		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Inspection Nos. 707800227, 700703643 and 696206130 observed unused equipment stored on the Location. Inspections required Operator to remove stored and unused equipment.  It was observed in this inspection that the unused equipment identified in the previous inspections remain stored on the Location. This CA has not been addressed and remains applicable.		
Corrective Action:	CA Per Inspection #707800227:  Remove stored/unused equipment	Date:	

Overall Good:

**Spills:**

Type	Area	Volume	
Comment:	Valve at the knock-out equipment on the northwest end of the Location is leaking, resulting in gas venting and fluids spilling onto the pad surface; broken glass also observed around areas of the spill.  At 12:10 hours, Operator on site (Dominic with the TEP Compliance Team) was provided notice of the leak/spill.		
Corrective Action:	Clean/remediate spill to Table 915-1 Cleanup concentrations.	Date:	12/26/2024
Other			
Comment:	Valve at the knock-out equipment on the northwest end of the Location is leaking, resulting in gas venting and fluids spilling onto the pad surface; broken glass also observed around areas of the spill.  At 12:10 hours, Operator on site (Dominic with the TEP Compliance Team) was provided notice of the leak/spill.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	12/11/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 383325 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Inspection #696206130 observed that interim areas Location are not progressing towards 1003 reclamation standards; perennial establishment is not uniform and Location is predominantly bare, or vegetated by Undesirable Plant Species including noxious weeds such as Jointed Goatgrass and Bulbous Bluegrass. Inspection required Operator to comply with 1002.f and 1003 rules by 11/15/2024.

Limited inspection due to snow cover, however, unable to find evidence that work to address the CA has been performed. Additionally, no resolution stating CAs have been completed pursuant to Rule 210.b has been submitted.

This CA has not been addressed and remains applicable.

Corrective Action

CA Per inspection #696206130:

Comply with Rule 1003.b and conduct additional reclamation efforts on the Location; Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Comply with Rule 1002.f and implement control measures to stabilize the seeded soil. Comply with Rule 1003.f and 606.c.: Ongoing weed and stormwater monitoring/management required until Location receives a passing final reclamation inspection.

Date \_\_\_\_\_

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
 Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
 Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
 1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_  
 Comment:   
 Corrective Action:  Date \_\_\_\_\_  
 Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
718100101	Leak at equipment	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821218">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821218</a>
718100102	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821219">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821219</a>