

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2024

Submitted Date:

12/10/2024

Document Number:

717000183

FIELD INSPECTION FORM

Loc ID 319893 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, PDC		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
Supervisor, ECME		jason.gomez@state.co.us	
,		conor.pesicka@state.co.us	
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201798	WELL	TA	03/30/2020	GW	001-07202	CHAMPLIN 67 AMOCO F UNIT 1	TA

General Comment:

[Follow-up inspection DOC #717000127](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type WEEDS

Comment: It appears that no steps have been taken to correct sight. doc#717000127 Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove all debris and weeds per Rule 606. Corrective Action Date 12/27/2024 days. See attached photo

Corrective Action: Remove all weeds around well head per Rule 606

Date: 12/27/2024

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date:

Type: Bradenhead # 1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 201798 Type: WELL API Number: 001-07202 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/23/2024 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 30 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: Appears to be plumbed to the surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary THIS IS A FOLLOW-UP INSPECTION FROM 11/1/2024 DOC #717000127 - NO CORRECTIONS APPEAR TO BE ADDERESD. On Friday December 4th at approximately 12:02pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection. Operator: PDC / Chevron Location name: CHAMPLIN 67 AMOCO F UNIT #1 API # 05-001-07202 Location ID #: 319893 County: Adams While there, I observed a TA well. During this inspection the following possible compliance issues were observed: Rule 606: Weeds, dead weeds. Within the designated setback (25 feet around any and all equipment), remove all debris and weeds around well head, per Rule 606. Corrective Action Date 12/27/2024 days. See attached photo # 1. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules. This is a summary of inspection report.</p>	finkenbc	12/10/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000184	Follow-up inspection photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821444