

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

713301392

## FIELD INSPECTION FORM

Loc ID 330534 Inspector Name: Kester, Michael On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
 Name of Operator: KP KAUFFMAN COMPANY INC  
 Address: 1700 LINCOLN ST STE 4550  
 City: DENVER State: CO Zip: 80203

**Findings:**

- 9 Number of Comments  
 1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251450	WELL	PR	10/01/2023	OW	123-19253	BAURER 41-36	PR

**General Comment:**[well site inspection](#)

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained Soil around well head MIRU 11-6-2024 Properly dispose of oily waste in accordance with 905.e.		
Corrective Action:	Comply with Rule 905e	Date:	12/27/2024

Overall Good:

**Spills:**

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	disassemble after MIRU 11-6-24		
Corrective Action:		Date:	

**Equipment:**

Type	Count	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Prime Mover	# 1				
Comment:	natural gas				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	
Type: Bradenhead	# 1				
Comment:	piped to surface				
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 251450 Type: WELL API Number: 123-19253 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 05/03/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents, conducted an on-site inspection,</p> <p>Location: Baurer 41-31 Operator: KPK API#: 123-19253 County: Weld</p> <p>While there, I observed well site with pumping unit During this inspection the following possible compliance issues were observed:</p> <p>Stained soil, Rule 905e corrective action date 12-27-2024</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC</p>	kesterm	12/11/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301393	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821503">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821503</a>