

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2024

Submitted Date:

12/11/2024

Document Number:

713301394**FIELD INSPECTION FORM**Loc ID 330652 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	<a href="#">all inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251613	WELL	PR	04/01/2023	OW	123-19416	EIBERGER 32-36	PR

**General Comment:**[well site inspection](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	OTHER	
Comment:	Stained Soil, MIRU 11-13-2024 Properly dispose of oily waste in accordance with 905.e	
Corrective Action:	Comply with Rule 905e	Date: 12/27/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	WELLHEAD	
Comment:	disassembled after rig work, MIRU 11-13-2024, doc 403992717	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	natural gas		
Corrective Action:		Date:	



**Inspected Facilities**Facility ID: 251613 Type: WELL API Number: 123-19416 Status: PR Insp. Status: PR**Producing Well**Comment: PR, Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 05/03/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>Inspector Michael Kester, did audit scout card and related documents, conducted an on-site inspection,</p> <p>Location: Eiberger 32-36 Operator: KPK API#: 123-19416 County: Weld</p> <p>While there, I observed well site with pumping unit During this inspection the following possible compliance issues were observed:</p> <p>Stained soil, Rule 905e corrective action date 12-27-2024, MIRU 11-13-2024, doc 403992717</p> <p>Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection</p>	kesterm	12/11/2024

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713301395	site pic	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821504">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6821504</a>