

Off-Location Flowline Photos
Flowline Facility ID 478121 & 478122
YE & YF Looplines

INSP Doc #714001501
FIRR #404021703
CA #200845 & 200857



Photo #1. View of above ground bollard cage, pipeline annulus vents, and corrosion protection sleeve located adjacent to the YE-7 P&A well location.



Photo #2. Close up view of the pipeline annulus vents supporting the YE Loopline near the YE-7 P&A well location.

WGS84 $\pm 19\text{ft}$ 37.49785, -108.80862 Δ $\pm 10\text{ft}$ 6747 ∇ ± 17 °,T N5



09Dec24 11:42 Ad-hoc

13220 County Road W, Yellow Jacket CO 81335, US © 09-Dec-24 11:42:35 AM

Photo #3. View of a tag on one of the two (2) existing pipeline annulus vents supporting the YE Loopline near the YE-7 P&A well location.

WGS84 37.49785, -108.80861 Δ ± 10 ft 6747 ∇ ± 15 °T NE63



09Dec24 11:42 Ad-hoc
13220 County Road W, Yellow Jacket CO 81335, US © 09-Dec-24 11:42:26 AM

Photo #4. View of the other tag on the two (2) existing pipeline annulus vents supporting the YE Loopline near the YE-7 P&A well location.

WGS84 $\pm 16\text{ft}$ 37.49785, -108.80859 \wedge $\pm 13\text{ft}$ 6755 ∇ ± 21 °,T NW329



Photo #5. View of the backside of the tags at the existing pipeline annulus vents supporting the YE Loopline near the YE-7 P&A well location.



Photo #6. View of above-ground YE-YF Loop Manifold which is located due north of the existing bollard cage (Photos #1 & #2). The pipeline annulus vent visible in the foreground of this photo has a tag that is labeled “YE Loop” and “Annulus Vent”