

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404021703

Date Received:  
12/12/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

0 CA Completed  
2 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LLC  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
General		CO2Source_Regulatory@kindermorgan.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001501  
Inspection Date: 10/25/2024 FIR Submit Date: 12/06/2024 FIR Status:

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LLC Company Number: 46685  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 313601

Location Name: YE (YELLOW JACKET)-N37N18W Number: 2NWNW County:  
Qtrqtr: NWN Sec: 2 Twp: 37N Range: 18W Meridian: N  
Latitude: 37.497860 Longitude: -108.809195

FACILITY - API Number: 05-083-00 Facility ID: 313601

Facility Name: YE (YELLOW JACKET)-N37N18W Number: 2NWNW  
Qtrqtr: NWN Sec: 2 Twp: 37N Range: 18W Meridian: N  
Latitude: 37.497860 Longitude: -108.809195

CORRECTIVE ACTIONS:

1 CA# 200856

Corrective Action: Abandon flowlines per rule 1105. Date: 01/06/2025

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Original Field Inspection Report (INSP Doc #693902003) dated 7/9/2020 stated that "a riser is present in the southeastern well pad area and does not appear to be associated with an active pipeline" and required removal

Operator Comment: of unused equipment/risers or documentation as to their use by 8/10/2020. In response, Kinder Morgan promptly submitted a FIRR noting that the "the equipment/risers identified during the COGCC inspection [are] in use and have been labeled appropriately," and that the "set of risers/equipment east of the YE-7 are annulus vents for the YE Cluster Production Loop line." This FIRR was approved by COGCC staff in September 2020. The equipment observed in the 2024 Field Inspection Report is still being used for these purposes. Kinder Morgan has submitted a Form 44 realignment report to clarify the alignment of the YE Loopline as it exists near the YE-7 location. See attached photolog and map for additional detail.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 200857

Corrective Action: remove (regardless of ownership) all debris, abandoned gathering line risers, and flowline risers, and equipment.

Date: \_\_\_\_\_

Response: FACTUAL REVIEW REQUEST

Basis for Review: Requested documentation was submitted prior to the inspection

Operator Comment: Original Field Inspection Report (INSP Doc #693902003) dated 7/9/2020 stated that "a riser is present in the southeastern well pad area and does not appear to be associated with an active pipeline" and required removal of unused equipment/risers or documentation as to their use by 8/10/2020. In response, Kinder Morgan promptly submitted a FIRR noting that the "the equipment/risers identified during the COGCC inspection [are] in use and have been labeled appropriately," and that the "set of risers/equipment east of the YE-7 are annulus vents for the YE Cluster Production Loop line." This FIRR was approved by COGCC staff in September 2020. The equipment observed in the 2024 Field Inspection Report is still being used for these purposes. Kinder Morgan has submitted a Form 44 realignment report to clarify the alignment of the YE Loopline as it exists near the YE-7 location. See attached photolog and map for additional detail.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Factual review request for the Corrective Actions which were completed and approved in 2020.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jenna Emerick

Signed: \_\_\_\_\_

Title: EHS Specialist

Date: 12/12/2024 7:48:33 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404021703	FIR RESOLUTION SUBMITTED
404025325	YE-YF Looplines Flowline Map
404025327	YE Loopline Photolog

Total Attach: 3 Files