

Inspection Photos
I-33 Flowline
Spill ID 481679/Remediation 23488



Photo 1 –

Photo 2 -

Inspection Photos
I-33 Flowline
Spill ID 481679/Remediation 23488



ECMC Environmental Inspection
40.06492, -104.99219, 1543.3m, 82°
12/04/2024 09:39:29 AM



ECMC Environmental Inspection
40.06493, -104.9922, 1544.0m, 74°
12/04/2024 09:39:23 AM

Photo 3 –

Photo 4 -

Inspection Photos
I-33 Flowline
Spill ID 481679/Remediation 23488



Photo 5 –



Photo 6 -

Inspection Photos
I-33 Flowline
Spill ID 481679/Remediation 23488



ECMC Environmental Inspection
40.06497, -104.9922, 1543.2m, 96°
12/04/2024 09:41:00 AM



ECMC Environmental Inspection
40.06497, -104.99219, 1543.2m, 61°
12/04/2024 09:41:03 AM

Photo 7 –

Photo 8 -

Inspection Photos
I-33 Flowline
Spill ID 481679/Remediation 23488



Photo 9 –

Photo 10 -