

**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3160 From entrance to location**



**Photo # 3161 From entrance to location**

**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3162 Location**



**Photo # 3163 Location**



**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3164 Location**



**Photo # 3165 Location**

Inspection Photos  
Location Name: QB Energy GMR 8-6 (K8W) Pad  
Location #: 311645



Photo # 3166 Location



Photo # 3167 Location





Inspection Photos  
Location Name: QB Energy GMR 8-6 (K8W) Pad  
Location #: 311645



Photo # 3168 Location



Photo # 3169 Location

**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3170 Location**



**Photo # 3171 Location**



**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3172 Location**



**Photo # 3173 Location**

**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3174 Location**



**Photo # 3175 Summit Midstream meter house not listed in  
FORM 2A/not in compliance with CECMC rules**



**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3176 Rupture disc vent line does not comply with CECMC pressure safety device rules**



**Photo # 3177 Rupture disc vent line does not comply with CECMC pressure safety device rules**

**Inspection Photos**  
**Location Name: QB Energy GMR 8-6 (K8W) Pad**  
**Location #: 311645**



**Photo # 3178 No FORM 4 SUNDRY submitted for liquid nitrogen tank**