

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/26/2024

Submitted Date:

12/06/2024

Document Number:

698602659

**FIELD INSPECTION FORM**Loc ID 304118 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10699

Name of Operator: OWN RESOURCES OPERATING LLC

Address: 305 S RIDGE STREET #6279

City: BRECKENRIDGE State: CO Zip: 80424

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

20 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
254092	WELL	PR	07/07/1997	GW	125-07970	KLINZMAN 10-11	PR

**General Comment:**

Routine Inspection.

**Location****Lease Road:**

Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good: ☐**Signs/Marker:**

Type	BATTERY		
Comment:	Well sign posted at remote Gas Meter Run.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No well lease sign posted at remote tank battery located at CR 52 & CR U.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	01/08/2025
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	Emergency contact information posted on well sign.		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	WEEDS		
Comment:	Dried weeds and vegetation around tank and equipment at production facility CR 52 & CR U.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Stock panel fencing around surface equipment at remote gas metering location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Vertical Separator	# 1		
Comment:	Inside separator shed on CR 52 & CR U.		
Corrective Action:		Date:	
Type: Dehydrator	# 1		
Comment:	Dehydrator on gas meter run inlet.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Separator Shed. CR 52 & CR U.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Tubing in the wellbore. Tubing valve not connected. Casing valve open.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located off access trail. Digital Gas Meter Run. Meter Calibration/Test Log dated 11-13-24. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Remote Gas Meter Shed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	PBV FIBERGLASS		,
Comment:	Tank is located across CR from remote metering location for Klinzman 9-11, 125-07864.				
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	None.			
Corrective Action:			Date:	

<b><u>Wells Served By Facilities Above</u></b>		<b><u>AirsID</u></b>	
API Number		API Number	AirsID
125-07864			
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	254092	Type:	WELL	API Number:	125-07970	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Tubing in wellbore. Tubing valve not connected. Casing valve open. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open.  Electronic Well File reflects last Production/Status reported 9/1/2024 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404018481	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813999">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813999</a>
698602677	Inspection photos.	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813977">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6813977</a>