

# Inspection Photos

Loc: 484357

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 12/12/2024

County: LAS ANIMAS




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward the location. There are vehicle driving over and damaging the stormwater wattles which will need to be replaced.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 2.** Facing toward the well where recent work with the rig was being conducted. There was a audible leak coming from the well and the operator onsite was notified.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 3.** Facing east at the location. There are several areas of oil stained soils that must be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 4.** There is oil stained soils at the drill rig which has no liner or containment. Stained soils will need to immediate clean up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 5.** There is fuel and lube oil containers not in containment shown at red arrows. The wattles are displaced in this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 6.** Facing east toward the flowline disturbance. The vegetation is not establishing along the flowline and there are vehicle tracks which a causing unnecessary disturbance. The flowline must be reclaimed and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

Inspection Photos



**Photo 7.** Facing northwest at the location.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 8.** There is red drill cutting sand that has spread onto the soil around the equipment. No liner or other containment is present.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024

## Inspection Photos



**Photo 9.** Standing on County Road 179 facing east toward DEO property. There is red drill cutting sand that has been spread on the road at Lat/Long:37.40116,-103.51736. E&P waste from the wellsite was not properly disposed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 12/12/2024