

Inspection Photos

Loc #: 481115

Operator: DESERT EAGLE OPERATING

Inspection Date: 12/12/2024

County: Las Animas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. There are vehicle tracks causing disturbance outside of the location. Vehicles must stay on access road boundary and wellsite only.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 481115 | Date: 12/12/2024

Inspection Photos



Photo 2. There is oil leaking from the wheel hub and stained soils that need to be cleaned up.



Inspection Photos



Photo 3. Facing southeast toward the wellsite. It appears recent work has been performed and the soils have been disturbed. The wattles are displaced and not maintained.



Inspection Photos



Photo 4. Facing toward the wellsite. There is white material waste around the well that must be cleaned up and properly disposed..



Inspection Photos



Photo 5. Facing south at the location. There are vehicle tracks along the flowline disturbance and vegetation is not establishing.



Inspection Photos



Photo 6. Facing east toward the flowline disturbance which has not established vegetation. Soils are not stabilized and are susceptible to erosion.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 12/12/2024

Inspection Photos



Photo 7. Facing southwest at toward the adjacent gas plant. Soils are caompacked in this area have not been reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc #: 481115 | Date: 12/12/2024

Inspection Photos



Photo 8. Facing toward the gas plant. There is a whit material that pushed and mixed in with soil which is adjacent to the wellsite. All waste material needs to be cleaned up and properly disposed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc #: 481115 | Date: 12/12/2024

Inspection Photos



Photo 9. South side of the location facing north. The disturbed soils are not establishing vegetation. Vehicle use has compacted the top soils.

