

Inspection Photos

12/10/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052

Inspection Doc: 718100105

Garfield County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



December 10, 2024



December 10, 2024

Photo 1: Photos taken from the working pad surface on the east end of the Location. Photo shows tracking/degradation; BMPs to stabilize, as well as to minimize erosion, degradation and sediment transport are no longer in proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



Photo 2: Photo taken from east end of the Location. Operator has placed an erosion blanket on a portion of the slopes. BMPs were not evident, or apparent, within remaining areas of concern identified within the previous inspection.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



December 10, 2024

Photo 3: See comments under photo 2. Photo shows interim areas/slopes on the east end of the Location where stormwater and reclamation issued were identified.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



Photo 4: See comments under photo 2 and 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



Photo 5: Photo shows areas of gully erosion on the northeast end of the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 335052



Photo 6: Photo taken from below the sediment trap on the southwest end of the Location. Sediment trap has not been installed with a properly engineered outlet; geotextile lining in conjunction with the rip-rap material not observed; slopes within outlet lacks stabilization and erosion degradation / sediment transport is evident



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources