

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2024

Submitted Date:

12/13/2024

Document Number:

715300036

FIELD INSPECTION FORM

Loc ID 332791 Inspector Name: Elnajdi, Abdul On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298854	WELL	PA	06/27/2023	OW	123-29172	HANSCOME C 28-28D	EI
298940	WELL	PA	05/28/2024	OW	123-29209	HANSCOME C 28-29D	EI
487293	SPILL OR RELEASE	CL	07/17/2024		-	Hanscome C28-29D	EI
487294	SPILL OR RELEASE	CL	07/16/2024		-	Hanscome C28-29D	EI

General Comment:

On THU Dec 12, 2024 at 1:00 PM. I, Abdul Elnajdi, conducted an enviromental inspection for HANSCOME C#28-28D and realted facilities. This is an environmental progress inspection. Any corrective actions from previous inspections that have not been addressed are still applicable. Photos attached to document site conditions. DURING THE INSPECTION, NO HAZARD THAT COULD POTENTIALLY IMPACT THE ENVIRONMENT WERE IDENTIFIED.

Inspected Facilities

Facility ID: 298854 Type: WELL API Number: 123-29172 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 298940 Type: WELL API Number: 123-29209 Status: PA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487293 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Facility ID: 487294 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715300037	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6824864