

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2024

Submitted Date:

12/13/2024

Document Number:

708905234

FIELD INSPECTION FORM

Loc ID: 334711 Inspector Name: Smelser, Wayne On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 30 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295301	WELL	PR	06/01/2024	GW	045-15721	LEVERICH FEDERAL 31-09D	PR
295304	WELL	PR	07/17/2009	GW	045-15722	LEVERICH FEDERAL 31-08D	PR
295305	WELL	PR	01/25/2009	GW	045-15723	LEVERICH FEDERAL 31-16D	PR
295306	WELL	PR	01/17/2009	GW	045-15724	LEVERICH 31-15B	PR
295311	WELL	PR	04/01/2024	GW	045-15729	LEVERICH 31-10B	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 12/12/2024 at approximately 11:20 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC LEVERICH 31-09 Pad. Location # 334711 in Garfield County Colorado. Location is within High Priority/Density/Black Bear Habitat areas. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Signs/Marker - Methanol tank improperly labeled/lacks required information with a CA date of 01/12/2025

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Methanol tank improperly labeled/lacks required information		
Corrective Action:	Comply with CECMC labeling rules		Date: 01/12/2025
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:

Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Pig station - pipe rail fence		
Corrective Action:			Date:
Type	OTHER		
Comment:	Summit Midstream meter house - pipe rail fence		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 5		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 5		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:	Summit Midstream		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	Unknown - tank not properly labeled	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	400 BBLs	STEEL AST		
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Centralized containment Unable to fully inspect secondary containment liner due to ice in containment			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	
Corrective Action:	
	Date:

Inspected Facilities									
Facility ID:	295301	Type:	WELL	API Number:	045-15721	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295304	Type:	WELL	API Number:	045-15722	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295305	Type:	WELL	API Number:	045-15723	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295306	Type:	WELL	API Number:	045-15724	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	295311	Type:	WELL	API Number:	045-15729	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, well on plunger lift							Date:	
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in some sections
		Compaction				Small amount of light compaction in some sections
				Material Handling And Spill Prevention		Chemical tank containment
Compaction	Fail					Lack of stabilization/compaction near battery
Gravel						Sparse to none in some visible areas

Comment: [Lack of stabilization/compaction on location near tank battery - please refer to photo log](#)
[Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Signs/Marker for corrective action & also refer to Stormwater for comments.	smelserw	12/13/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905235	Inspection 708905234 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825143
708905236	Inspection 708905234 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825144