



FORM  
INSP  
  
Rev  
X/20

State of Colorado  
Oil and Gas Conservation Commission  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:  
12/09/2024  
Submitted Date:  
12/14/2024  
Document Number:  
715201308

Loc ID  
485672

Inspector Name:  
Welsh, Brian

On-Site Inspection ☐  
2A Doc Num: \_\_\_\_\_

**Operator Information:**  
ECMC Operator Number: 10791  
Name of Operator: WAVETECH HELIUM INC  
Address: 1801 BROADWAY SUITE 600  
City: DENVER State: CO Zip: 80202

**Status Summary:**  
☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED  
**Findings:**  
9 Number of Comments  
0 Number of Corrective Actions  
☐ Corrective Action Response Requested  
**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Jobe, Patrick	(303) 534-3383	pjobe@wavetechenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
486311	WELL	DG	06/13/2024		017-07820	1 Wavetech FPI Burlington Farms 32-11	WK

**General Comment:**

SE Compliance Specialist Brian Welsh conducted a routine field inspection of the well location and equipment

Date Run: 12/14/2024 Doc [#715201308]

Page 1 of 5

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Lease sign by county road		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by acces at location entrance		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Flare	# 1		
Comment:	Flare set up for well testing		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Well testing equipment on location		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	LVST		39.028000,-102.193020
Comment:	Frac tank on location for swabbing				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	



Inspected Facilities									
Facility ID:	486311	Type:	WELL	API Number:	017-07820	Status:	DG	Insp. Status:	WK
Workover									
Comment: <div>Codell Well Service on location to swab and test the well</div>									
Corrective Action: <div></div> Date: <div></div>									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Berm on south side of location from location construction

Corrective Action: Date:

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (https://ecmc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
715201325	location photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825418