

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2024

Submitted Date:

12/15/2024

Document Number:

713400539

## FIELD INSPECTION FORM

 Loc ID 312633 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_
**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**12 Number of Comments1 Number of Corrective Actions

- 
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Toews, Wesley		wtoews@blm.gov	
Kellerby, Shaun		shaun.kellerby@state.co.us	
, LARAMIE		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222062	WELL	PR	09/01/2024	GW	077-08664	HORSESHOE CANYON 3-34	PR

**General Comment:**[CECMC Inspection Report Summary](#)

On 12/10/2024 at approximately 14:01 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Horseshoe Canyon/3-34 Pad at Location ID #312633 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

1. Signs/Marker - No tank battery signage with a CA date of 01/15/2025

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Access	
	Corrective Action:		Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	OTHER	
	Comment:	Sign at entrance to location - Sign is weathered & cracked but still legible	
	Corrective Action:		Date:
	Type	WELLHEAD	
	Comment:		
	Corrective Action:		Date:
	Type	OTHER	
	Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.	
	Corrective Action:		Date:
	Type	TANK LABELS/PLACARDS	
	Comment:		
	Corrective Action:		Date:
	Type	BATTERY	
	Comment:	No tank battery signage, refer to photos	
	Corrective Action:	Comply with CECMC signage rules	Date: 01/15/2025

Emergency Contact Number:

	Comment:	1-800-891-6191/911	
	Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No \_\_\_\_\_

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	WELLHEAD	
	Comment:	Pipe rail fencing	
	Corrective Action:		Date:
	Type	TANK BATTERY	
	Comment:	Hog panels	
	Corrective Action:		Date:

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:	No form of pressure monitoring equipment. Bradenhead valve is accessible	
Corrective Action:		Date:
Type: Deadman # & Marked	# 3	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		
Comment:	Tank not equipped with telemetry				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	62 bbls
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent		
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 222062 Type: WELL API Number: 077-08664 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
		Ditches				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker for corrective action.</a>	popejoyd	12/15/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400540	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825916">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6825916</a>