

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3065 From entrance to location




Photo # 3066 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3067 Location



Photo # 3068 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3069 Location



Photo # 3070 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Dec 11, 2024 at 1:09:32 PM
CO



Dec 11, 2024 at 1:11:11 PM
CO

Photo # 3071 Location

Photo # 3072 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3073 Location



Photo # 3074 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3075 Staining around RU 43-6 wellhead




Photo # 3076 Tank label contains inaccurate information

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3077 Unused hose on tank battery stairs



Photo # 3078 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Federal RU 34-6 Pad

Location ID: 335044



Photo # 3079 Multiple open ended piping on separator unit/wildlife hazards/available for entry by wildlife

