

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2024

Submitted Date:

12/09/2024

Document Number:

698602698**FIELD INSPECTION FORM**Loc ID 337238 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10699Name of Operator: OWN RESOURCES OPERATING LLCAddress: 305 S RIDGE STREET #6279City: BRECKENRIDGE State: CO Zip: 80424**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
-
- 2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat	970-332-3585	pat.dolezal@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284351	WELL	PR	04/19/2006	GW	125-09951	JOSH 21-4 4N46W	PR

General Comment:[Follow-up Inspection.](#)

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign at wellhead location.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign.

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Produced Water	WELLHEAD	<= 1 bbl		
Comment:	Active release at wellhead. Less than 1 barrel.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date: 12/05/2024

In Containment: No

Comment: Well had previous active release at wellhead from check valve. Repair work disconnected water leg from wellhead tree. Current leak is from broken gauge used a plug on riser at wellhead.

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around surface equipment at well location.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Wellhead. Casing production. Rods and tubing in the wellbore. Tubing valve not connected. Casing valve open. Well had previous active release at wellhead from check valve. Repair work disconnected water leg from wellhead tree eliminating pressure at the check valve. Current leak is from broken gauge face used a plug on riser plug at wellhead.		
Corrective Action:	Operators will promptly investigate, and if appropriate, repair, replace, or remediate any malfunctioning equipment or process. Comply with Rule 609.a.		Date: 12/05/2024

Venting:

Yes/No	NO		
Comment:	Current release at well is from isolated water line.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284351	Type:	WELL	API Number:	125-09951	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods and tubing in wellbore. Tubing valve not connected. Casing valve open.								
Corrective Action:								Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Follow-up inspection completed to verify Operator corrective actions for corrective action issued from routine inspection completed 9-24-24 document number 698602401. At time of follow-up inspection additional release was noted at water line resulting from wellhead repair work to correct previous corrective action. Notified Field Foreman 9/4/24.	stjohnw	12/09/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404020649	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817149
698602729	Inspection photos.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817147
698602730	Release from water line.	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817148