

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2024

Submitted Date:

12/09/2024

Document Number:

710100311

FIELD INSPECTION FORM

Loc ID: 475409
Inspector Name: Anderson, Laurel
On-Site Inspection:
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 6 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|-----------------|
| | | ECMCInspections@Oxy.com | All Inspections |
| Brown, Kari | | kari.oakman@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|--------------|--------|-------------|------------|-----------|---------------------------|-------------|
| 295051 | WELL | TA | | OW | 123-25654 | STROMQUIST 22-21 | TA |
| 487626 | TANK BATTERY | AC | 08/20/2024 | | - | Stromquist 14-21 Facility | EI |

General Comment:

ECMC Environmental Inspection of the following Kerr McGee (Operator) facilities:
Stromquist 14-21 Tank Battery Facility ID 487626
Remediation Project No 36866
Stromquist 22-21 Wellhead API 123-25654
Remediation Project No 36608

Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:

Stromquist 14-21 Tank Battery Facility ID 487626/Remediation Project No 36866:

- Weeds
- Unused equipment
- Form 27s Doc #403997692 received 11/18/2024 currently in process.

Stromquist 22-21 Wellhead API 123-25654/Remediation Project No 36608:

- Open excavation infiltrated with groundwater
- Soil stockpiled on location with inadequate BMPs
- Form 27s Doc #403987402 received 11/11/2024 currently in process.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused equipment being stored at tank battery. | | |
| Corrective Action: | Comply wiith Rule 606. | Date: | 12/23/2024 |
| Type | WEEDS | | |
| Comment: | Weeds throughout tank battery. | | |
| Corrective Action: | Comply with Rules 606.c. and 1003.f. | Date: | 12/23/2024 |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 295051 Type: WELL API Number: 123-25654 Status: TA Insp. Status: TA

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487626 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment: [Remediation Project No 36866 open - Form 27 in process](#)
[Remediation Project No 36608 open - Form 27 in process](#)

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____

Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Soil is stockpiled adjacent to the wellhead excavation with no BMP's present.](#)

Corrective Action: [Manage stockpiles in compliance with Rule 1002.\(c\). Manage waste in compliance with Rule 913.b.\(3\) and ECMC Guidance 913.b.\(5\)B.i-v.](#)

Date: 12/10/2024

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 404021245 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817679 |
| 710100312 | Photo Documentation | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6817674 |