

# Inspection Photos

Loc: 483008

Operator: BNL (ENTERPRISE) INC

Inspection Date: 12/12/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northeast along the access road. There are areas of the road that will need to be repaired and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483008 | Date: 12/12/2024

## Inspection Photos



**Photo 2.** Facing toward the northwest side of the location. The silt fence is not maintained at the location. The loose soils along the access road at red arrow are not stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:483008 | Date: 12/12/2024

## Inspection Photos



**Photo 2.** Facing toward the northwest side of the location. The silt fence is not maintained at the location.



## Inspection Photos



**Photo 4.** Facing southeast toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Loc:483008 | Date: 12/12/2024

## Inspection Photos



**Photo 5.** Facing toward the well.



**Photo 6.** The open cellar at the wellhead does not have adequate wildlife protections..



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos



**Photo 7.** Facing toward the topsoil pile at the south side of the location. There is erosion occurring along the topsoil which is not stabilized or protected..



## Inspection Photos



**Photo 8.** South side of the location facing westtoward the topsoil pile. The topsoil has not been seeded and is not stabilized. The perimeter silyt fence is not maintained.



## Inspection Photos



**Photo 9.** Facing toward the northeast side. This brush pile debris needs to be removed.



## Inspection Photos



**Photo 10.** North side of the location facing west.

