

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/15/2024

Submitted Date:

12/09/2024

Document Number:

710100315

**FIELD INSPECTION FORM**

Loc ID 336262 Inspector Name: Anderson, Laurel On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 47120  
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
Address: P O BOX 173779  
City: DENVER State: CO Zip: 80217-

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
,		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
487372	TANK BATTERY	AC	07/30/2024		-	Stromquist 13,23,34&35-21 Facility	EI

**General Comment:**

ECMC Environmental Inspection of the following Kerr McGee (Operator) facilities:  
Stromquist 13,23,34&35-21 Facility - #487372  
Remediation Project No 36844  
Any corrective actions from previous inspections, forms, or orders that have not been addressed are still applicable. There were no Operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Current site status:  
Overgrown weeds throughout entire location  
Debris/trash from shredded/falling apart protective shielding around aboveground piping/equipment  
Form 27s DOC #403991117 received on 11/12/2024 is in process.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris/trash from shredded/falling apart protective shielding around aboveground piping/equipment.		
Corrective Action:	Comply with Rule 606.	Date:	12/23/2024
Type	WEEDS		
Comment:	Overgrown weeds throughout entire tank battery.		
Corrective Action:	Comply with Rules 606.c. and 1003.f.	Date:	12/23/2024

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 487372 Type: TANK API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404021477	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6818139">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6818139</a>
710100316	Photo Documentation	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6818138">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6818138</a>