

# Inspection Photos

Loc #: 484359

Operator: DESERT EAGLE OPERATING

Inspection Date: 12/12/2024

County: Las Animas



Inspection Photos



**Photo 1.** Facing southeast toward the wellsite.



## Inspection Photos



**Photo 2.** Facing southeast. The vegetation is not establishing at the location and soils are not stabilized.



## Inspection Photos



**Photo 3.** Facing toward the wellsite. It appears recent drilling work was performed at the location and red cuttings were left behind around the wellhead. E&P waste was not properly managed. The fencing and sign were removed from the well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc #: 484359 | Date: 12/12/2024

## Inspection Photos



**Photo 4.** Facing north toward the wellsite. It appears recent drilling work was performed at the location and red cuttings were left behind around the wellhead. E&P waste was not properly managed. There is also oil stained soil at red arrow.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc #: 484359 | Date: 12/12/2024

## Inspection Photos



**Photo 5.** Facing north at the location. The wattles at left side of the photo are not installed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc #: 484359 | Date: 12/12/2024